






NOTE
POWER SUPPLY WIRING
MUST HAVE CORRECT
POLARITY AND GROUNDING
FOR THE UNIT TO
OPERATE CORRECTLY.



PRESSURE SWITCH



⚠ WARNING

Some internal parts are not grounded and may present a risk of electrical shock when servicing. **SERVICE PERSONNEL, DO NOT** contact the motor or motor control when the machine is plugged in.

⚠ WARNING

Failure to install, maintain, and/or operate this machine according to manufacturer's instructions may result in conditions which can produce bodily injury and/or property

SPRAY RINSES = COLD

WHT/GRY
VLT
BRN/WHT
ORG/BLK
RED/YEL

5 4 3 2 1

